



Life Safety Survey Summary

*28 AL surveys reviewed; 10 programs received no insufficiencies

IFC	DEFICIENT PRACTICE
5.1.1	Sprinkler Systems- General (1 insufficiency)
6.2.9	Stock of Spare Sprinklers (1 insufficiency)
13.1.1	Sprinkler Systems- General (1 insufficiency)
110.26	Electrical Panels Working Space (1 insufficiency)
315.3.1	Combustible Materials Storage Requirements (1 insufficiency)
405.2	Assisted Living Drills (1 insufficiency)
405.5	2015 IFC (1 insufficiency)
605.1	Electrical Abatement (2 insufficiencies)
703.1	Fire Resistance-Rated Construction- Maintenance (2 insufficiencies)
703.2	Opening Protectives (2 insufficiencies)
703.2.2	Door Hold- Open Devices and Closers (3 insufficiencies)
703.2.3	Door Operation (2 insufficiencies)
716.5.9.2	Automatic – Closing Fire Door Assemblies (1 insufficiency)
901.6.1	Sprinkler systems—inspections & testing (1 insufficiency)
907.1	Fire Alarm- 2015 IFC (1 insufficiency)
907.8.2	Fire Alarm Testing (1 insufficiency)
907.8.3	Smoke Detector Sensitivity (3 insufficiencies)
1008.3.1	Means of Egress Illumination- Emergency Power (1 insufficiency)
1031.2	Maintenance of Means Egress (1 insufficiency)