



Life Safety Survey Summary

*12 AL surveys reviewed; 3 programs received no insufficiencies

IFC	DEFICIENT PRACTICE
5.2.1	Standard for the Inspection, Testing, and Maintenance of Water-Based Fire Protection Systems (2 insufficiencies)
5.3.2	Sprinkler Systems- Gauges (1 insufficiency)
6.2.9	Stock of Spare Sprinklers (1 insufficiency)
14.2.1	Assessment of Internal Condition of Piping (1 insufficiency)
210.8	Ground - Fault Circuit Interrupters (GFCI outlets) (1 insufficiency)
315.3.1	Combustible Materials Storage Requirements (2 insufficiencies)
405.2	Assisted Living Drills (2 insufficiencies)
605.1	Electrical Abatement (2 insufficiencies)
703.1	Fire Resistance-Rated Construction- Maintenance (4 insufficiencies)
703.2.2	Door Hold- Open Devices and Closers (1 insufficiency)
901.6.1	Sprinkler systems—inspections & testing (2 insufficiencies)
906.2	General Requirements: Fire extinguishers (2 insufficiencies)
904.12.5	Commercial Cooking System- Portable Fire Extinguishers (1 insufficiency)
907.8.2	Fire Alarm Testing (1 insufficiency)
907.8.3	Smoke Detector Sensitivity (2 insufficiencies)
1008.3	Means of Egress Illumination- Emergency Power (1 insufficiency)
4603.7	Single and Multiple Station Smoke Alarms (1 insufficiency)